Product Data
Hempel's Wax TecCel™

HEMPEL

Description:	HEMPEL'S WAX TecCel 69034 is a high performance liquid wax with TecCel technology providing a long lasting, deep gloss finish with excellent protection.
	TecCel is the mark of HEMPEL'S advanced performance coatings, containing polytetrafluorethylene, giving significant improvements in performance.
Recommended use:	For use on gelcoat, painted and varnished surfaces after polishing with HEMPEL'S CUSTOM MARINE POLISH 67444.
	Leaves an easy to clean, water repellent surface with long-lasting protection. Suitable for both manual and machine use
Availability:	Part of European Yacht assortment. Local availability subject to confirmation.

PHYSICAL CONSTANTS:

Shade nos/Colours:	09990/ Off-white.
Flash point:	80 °C [176 °F]
Specific gravity:	1 kg/litre [8 lbs/US gallon]
pH:	8.3
VOC content:	214 g/l [1.8 lbs/US gallon]

The physical constants stated are nominal data according to the HEMPEL Group's approved formulas.

APPLICATION DETAILS:

Safety:	Handle with care. Before and during use, observe all safety labels on packaging and paint containers, consult HEMPEL Safety Data Sheets and follow all local or national safety regulations.
SURFACE PREPARATION:	Clean and degrease the surface with HEMPEL'S PRE-CLEAN 67062 or HEMPEL'S BOAT SHAMPOO 67284 to remove dirt and other contaminants, rinse with fresh water. . **Surfaces in good condition:** Polishing with: HEMPEL'S CUSTOM MARINE POLISH 67444. Apply: HEMPEL'S WAX TecCel 69034. **Deteriorated surfaces:** Use:HEMPEL'S RUBBING LIQUID 69021 to restore and renew gloss and colour of gelcoat and painted surfaces followed by: HEMPEL'S CUSTOM MARINE POLISH 67444. Apply: HEMPEL'S WAX TecCel 69034.
PRODUCT APPLICATION:	Shake well before use. Apply the product in a thin layer with clean, soft rags. Treat only small areas at a time. Allow the surface to dry. Polish using a clean, soft cloth or a polishing machine to obtain a more effective performance. Change to clean cloths frequently. Use a new, clean polishing pad when using the polishing machine. To maintain the high gloss performance, apply extra layers when first signs of gloss decrease are observed. Allow freshly painted surfaces to dry/cure for at least 90 days before applying the product. Later if repainting is required, it is very important to remove all traces of wax by using: HEMPEL'S PRE-CLEAN 67602. Rinse the surface with fresh water.
APPLICATION CONDITIONS : REMARKS:	Do not expose to frost. Do not apply in direct sunlight. The temperature should not be below: 5°C/41°F.
Note:	**HEMPEL'S WAX TecCel™ 69034**
ISSUED BY:	HEMPEL A/S 6903409990